

Arizona Construction Equipment Inspection Form

Make: JCB **Model:** 407 **Year of Manufacture:** 2015 **Type:** Loader **Hours:** 2026

Product Identification Number: JCB407P0A02092243

Engine Make: Kohler **Engine Serial:** 4511001400 **Power:** 64HP@2200 RPM **Tier:** 4

Drive: Hydrostatic All Wheel Drive

ROPS: Open. Yellow trim piece that covers top of ROP has piece broken off in the front left area.

Tires

Front Left: Dunlop SP T9 365/70R18	Life:75%
Front Right: Dunlop SP T9 365/70R18	Life:75%
Rear Left: Michelin 340/80R18 (MISS MATCH)	Life:40%
Rear Right: Dunlop SP T9 365/70R18	Life:40%

Operation: Started up with no problems. Drives and shifts as designed. Operational controls and gauges work properly.

Fluids

Hydraulic Fluid: Full
Engine Oil: Full but dirty.

Air Filter: Dirty, recommend replacing.

Control Valves: Show signs of slight weepage.

Bucket

Manufacture: JCB Year: 2013 Capacity: 22.3ft³ [.83yd³] Serial Number: 2030297

Additional Comments: Bucket is in overall good condition but does not have a cutting edge. Bucket's parallel lift works properly. Locking levers are broken and missing off of the bucket that connect to quick connect assembly.

Quick Attach: Right side pin is leaking hydraulic fluid. (When engaging lever to lock/unlock). Double acting cylinder.

Lights

Headlights: Functional.
Turn Signals Front: Functional.
Turn Signals Rear: Left side does not work.
Brake lights: Functional.

Mirrors: Driver side mirror missing.

Horn: Functional.

Seat: Upholstery is in good condition no rips or tears. Seat is in lowered position and was unable to raise height.

Cosmetics, Visuals and Additional Comments: Machine is dirty, needs cleaning. Paint is in good condition. Engine area is clean. Scratches on rear left and rear right of machine. Needs new JCB decals. Safety bracket missing on left side of lifting arm. Instruction manual is present.