

P.O. Box 31279 Phoenix, AZ 85046-1279 Tel: (602) 257-0802 www.azce.com

## **Arizona Construction Equipment Inspection Form**

Make: JCB Model: 3CX Compact Year of Manufacture: 2016 Hours: 659.1

Type: Loader Backhoe Product Identification Number: JCB3CX12CG2495555

**Engine Make:** Kohler **Power:** 74HP@2200 RPM **Tier Rating:** Tier 4 Final

Engine Serial: ED3N92D0-14615901200

**Drive:** Hydrostatic all-wheel drive, four-wheel and two-wheel steer equipped.

**Operation:** Started up with no problems. Mechanically everything operable and tight. Drives and shifts as designed. Operational controls and gauges work properly. Backup alarm does not work and when in reverse there is slight clicking noise. The clicking noise might be due to the backup alarm not functioning properly. Could be a tell-tale.

**EROPS:** Air condition and heating work. Front and rear wiper blades work. Needs washer fluid.

Tires: All matching Michelin 340/80-18, like new condition.

Fluids Air Filter: Dirty, recommend replacing.

Hydraulic Fluid: Low. Engine Oil: Full but dirty.

## **Front Bucket**

Manufacture: JCB Year: 2016 SAE Capacity: 0.92yd<sup>3</sup> Width: 78" Part Number: 2030297 **Additional Comments:** Bucket is in very good condition, has bolt on cutting edge. Bucket's parallel lift works properly. Quick connect assembly system works as designed.

**Rear Bucket:** Width 16". Extendahoe functions as designed. No slop, movement is tight.

## Lights

Headlights: Functional. Turn Signals Front: Functional. Turn Signals Rear: Functional. Brake Lights: Functional. Front Work Lights: Functional. Rear Work Lights: Not Functional.

**Mirrors:** Functional. **Horn:** Functional.

**Seat:** Cloth upholstery is in good condition no rips or tears. Headrest is missing. Suspension seat is missing front lever to control front, back and swivel functions. Currently there is metal wire to pull on to use swivel function. Recommend repairing seat's front lever to allow full functionality.

**Cosmetics, Visuals and Additional Comments:** Overall mechanical condition is good to excellent. Machine is dirty, needs cleaning. Paint is in good condition, still bright yellow. Scratches and nicks on inside of stick and front center of machine. Instruction manual is present.